

UTAH DEPARTMENT OF NATURAL RESOURCES - DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210, Salt Lake City UT 84116 (Delivery service)
Box 145801, Salt Lake City UT 84114-5801 (US Postal service)
Telephone: (801) 538-5342

LARGE MINING OPERATIONS PROGRESS REPORT
January 1, 2015 to December 31, 2015

RECEIVED

FEB 01 2016

DIV. OF OIL, GAS & MINING

The information required in this form is based on provisions of the Mined Land Reclamation Act, Title 40-8, and the R647 rules under the Utah Minerals Regulatory Program. It is due January 31 of each year. Attach additional pages as needed.

1. Mine Permit Number: M/049 /005
2. Mine Name: Jim Gay Mine
3. Name of Operator/Permittee: Pabco Clay Products LLC, dba Interstate Brick Company
Note: If Operator's address, company representative and/or phone number have changed, submit replacement page(s) for the Notice of Intention together with form MR-REV available on the Division's web page at https://fs.ogm.utah.gov/pub/MINES/Minerals_Related/FORMS/MR-REV.pdf.

4. Report the gross amount of ore or product mined and waste moved.

Gross ore or product mined 11,480 (amount) tons (unit)

Waste material moved see 7. below (amount) (unit)

Disposition of ore and waste: clay stockpiled to be hauled offsite. Overburden salvaged for topsoil.

Primary Commodities Produced clay

5. Total disturbed area from previous reporting year 64 Acres
New disturbance created during current reporting year 0 Acres
Total disturbed area at the end of this reporting year 64 Acres* Area was gpsed with DOGM 2/15 for bond adjustment.

* The total disturbed area includes reporting year and previous year disturbances minus areas of regrading and reseeding that have received approval for bond release. The Total area should not be greater than the permitted/bonded acreage.

6. Areas of reclamation eligible for bond release:
Areas regraded during the year (-) 0 Acres**
Areas reseeded during the year (-) 0 Acres**

** To apply for full or partial bond/site release submit form MR-SITE available at the Divisions web page at https://fs.ogm.utah.gov/pub/MINES/Minerals_Related/FORMS/MR-SITE.pdf.

7. Briefly describe reclamation work performed during current reporting year. If there was no production shown in Line 4, describe any maintenance work conducted that required earthmoving equipment. Include an updated map depicting surface disturbance and reclamation performed during the year (per R647-4-121.2) and any updates to the operation plan (per R647-4-106).

The rock wall on the eastern edge of the mining area was put in the old pit area from prior mining which is part of reclamation contouring.

I hereby certify the information provided in this report is true and correct to the best of my knowledge and belief.
Name (Typed or Print): John Hewitt

Title of Operator: Assistant Plant Manager


Signature of Operator: [Signature]

Date: 1/28/16

2015 MR-AR Annual Report Map

Jim Gay Mine, M/490/005

Pabco Clay Products, LLC dba Interstate Brick









Copyright © 2013 ESRI, Inc., GeoEye

0 0.1 0.2 0.4 Kilometers

scale 1:8,000

0 0.05 0.1 0.2 0.3 0.4 0.5 Miles

Legend

-  Area Mined in 2015
-  Rock OB redistributed into former mine trench
-  Clay Stockpile
-  2015 disturbed area - 57 acres
-  23 acres owned by ISB in SW corner of Section
-  Davis lease area boundary



Soldiers Pass Quadrangle Map
T7S, R1E, SW4SW4 Sec 7
T7S, R1E, NW4NW4 Sec 18
T7S, R1W, NE4NE4 Sec 13
T7S, R1W SE4SE4 Sec 12
as of April 2003, JH